



Lower electrical resistivity zone isolates seepage zones identified at the dam fill contact with native soil. IP anomaly provides additional confirmation of fluid flow at this location.

